

# ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE REGULATORY CONTACT RECORD

---

**Date/Time:** December 16, 2004 / 0830

**Site Contact(s):** Robert Richardella  
**Phone:** 303-966-6325

**Regulatory Contact:** Denise Onyskiw  
**Phone:** 303-692-3371

**Agency:** CDPHE

---

**Purpose of Contact:** Discuss an additional opening in the wall of Bldg 559, Room 129

---

## Discussion

On November 17, 2004, a contact record was generated that addressed a breach in the wall of room 129 as follows: in order to remove this plenum, the exterior wall of building 129 will be breached, where the plenum intake is located, and the plenum waste removed through this breach. Once the plenum is removed the breach will be contained with plastic containment.

Project management has determined that instead of breaching the wall where the plenum is, a breach in this same east wall is needed south of the multizone plenum in order to load waste into cargo containers. The size of the opening will be 12 feet wide by 11 feet high.

Ms. Onyskiw agreed to this approach with the following conditions: 1) when the cargo is up against the building it will be sealed with plastic to prevent any possible release to the environment; 2) when a cargo is not in place the opening will be sealed; and 3) negative airflow will be maintained from room 129 into the building CA.

---

**Contact Record Prepared By:** Kim Myers

---

## Required Distribution:

M. Aguilar, USEPA  
S. Bell, DOE-RFPO  
B. Birk, DOE-RFPO  
C. Deck, K-H Legal  
D. Foss, K-H 707/776/777

R. Leitner, K-H 371/374  
J. Mead, K-H ESS  
G. Morgan, DOE-RFPO  
S. Nesta, K-H RISS  
K. North, K-H ESS/MS

## Additional Distribution:

R. Richardella, 559 Project  
D. Onyskiw, CDPHE  
D. Kruchek, CDPHE

---

---

Contact Record 4/10/00  
Rev. 5/24/04

1/2

S. Garcia, USEPA  
C. Gilbreath, K-H 771/774  
S. Gunderson, CDPHE  
J. Legare, DOE-RFPO


R. Schassburger, DOE-RFPO  
D. Shelton, K-H ESS  
C. Zahm, K-H Legal

---

---

---

---



2/2